

COPPER CHIP POTS CARE INSTRUCTIONS

Commercial copper cleaners often contain harsh chemicals, but you can naturally clean copper with materials usually already found at home.

CLEANING

- **Vinegar and Salt:** Rub a mixture of 1 tablespoon of table salt and 1 cup of white vinegar onto the copper with a soft cloth and rinse.
- **Ketchup:** A small amount of this common kitchen condiment can be rubbed onto tarnished copper to restore its natural luster. Then rinse and dry.
- **Lemon:** Cut a lemon in half, add salt to the cut side and rub gently onto the item. You can also make a paste with lemon juice, and equal parts salt and non-oxidized cornstarch or baking soda.
- **Baking Soda:** Combine this mineral with lemon juice to clean copper naturally, or sprinkle just baking soda onto a cloth and polish the tarnished copper.